



2244 W McDowell  
Phoenix, AZ 85009  
1-800-274-RACE  
FAX: 602-340-8429  
602-257-9591

## HP9400 – CHEVY SFI FLEX SHIELD

1. Cut off ears on both sides of transmission.
2. Remove 4 bolts from bell housing.
3. Position flex-plate shield over transmission, replace bolts and tighten.



2244 W McDowell  
Phoenix, AZ 85009  
1-800-274-RACE  
FAX: 602-340-8429  
602-257-9591

## HP9400 – CHEVY SFI FLEX SHIELD

1. Cut off ears on both sides of transmission.
2. Remove 4 bolts from bell housing.
3. Position flex-plate shield over transmission, replace bolts and tighten.



2244 W McDowell  
Phoenix, AZ 85009  
1-800-274-RACE  
FAX: 602-340-8429  
602-257-9591

## HP9400 – CHEVY SFI FLEX SHIELD

1. Cut off ears on both sides of transmission.
2. Remove 4 bolts from bell housing.
3. Position flex-plate shield over transmission, replace bolts and tighten.